



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20LA121



Photo 1 – View of Airplane from Rear (Photo Courtesy of FAA)



Photo 2 – View of Airplane From Left (Photo Courtesy of FAA)



Photo 3 – View of Airplane from Right (Photo Courtesy of FAA)



Photo 4 – View of Airplane from Front (Photo Courtesy of FAA)



Photo 5 – View of Left Wing Damage (Photo Courtesy of FAA)



Photo 6 – View of Propeller (Photo Courtesy of FAA)



Photo 7 – Engine Prior to Inspection (Photo Courtesy of John DeYager)