



## **Memorandum For Record**

**Timothy W. Monville**  
**Sr. Air Safety Investigator**  
**Eastern Region**

---

**Date: March 22, 2022**  
**NTSB Accident Number: ERA20LA202**

---

A 27 second video segment taken from a security camera located at the San Juan Bay Marina, whose address was 482 Avenue Fernandez Juncos, San Juan, Puerto Rico 00902 was provided to NTSB by the Federal Aviation Administration investigator-in-charge.

The video clip depicted the final portion of the flight and the area where the airplane impacted the water. At 0:02 seconds elapsed time, the airplane came into view of the left side of the frame and continued in a wings level slight nose-up attitude until about 0:17 seconds elapsed time (Figure 1). One of the landing gears is visibly extended at 0:17 seconds elapsed time.

At 0:17 seconds elapsed time the airplane began a left turn briefly which was arrested in a shallow left bank and slight nose-up pitch attitude, but as the flight continued over the next 5 seconds to 0:22 elapsed time, the bank angle increased to the left to an inverted position and the airplane began a nose-low descent (Figure 2), which continued until the airplane went out of view (Figure 3). A splash in the water was noted.

No parts were noted separating from the airplane in-flight and no smoke was noted trailing the airplane.




Figure 1: Screenshot Capture from Security Video. Taken at 0:17 seconds elapsed time. Note the Airplane in a slight left bank and nose-up attitude.




Figure 2: Screenshot Capture from Security Video. Taken at 0:22 seconds elapsed time. Note the Airplane in an inverted and nose-low attitude.




Figure 3: Annotated Video ScreenShot Capture. Arrow Points to Airplane Before Water Impact.