



Photo 1 – Piper Digital Photograph. Left Side View of the Airplane Following Recovery. Note the Separated Left Wing.



Photo 2 - Piper Digital Photograph. View of the Separated Left Wing with Attached Engine and Propeller Assembly.



Photo 3 - Piper Digital Photograph. Right Forward Quartering View of the Fuselage, Engine Assembly with Attached Propeller, and Portion of the Right Wing.



Photo 4 - Piper Digital Photograph. View of the Right Side of the Left Engine Assembly with Attached Propeller.



Photo 5 - Piper Digital Photograph. View of the Right Side of the Right Engine Assembly with Attached Propeller



Photo 6 - Piper Digital Photograph. View of the Instrument Panel. Note the Positions of the Throttle, Propeller, and Mixture Controls.




Photo 7 – NTSB Digital Photograph. View of the Left Engine Servo Fuel Injector During Bench Testing Conducted Virtually.




Photo 8 - NTSB Digital Photograph. View of the Contaminant Found Between the Mixture and Idle Valves of the Left Engine Servo Fuel Injector. A better Photograph was not available.



Photo 9 - Piper Digital Photograph. View Showing the Separated Throttle Control Cable at the Left Servo Fuel Injector.