



Photo 1 – View of Main Wreckage at Accident Site (NTSB)



Photo 2 - View of Main Wreckage at Accident Site (NTSB)



Photo 3 – Front View of Main Wreckage at Accident Site (NTSB)



Photo 4 – Right Side View of Main Wreckage at Accident Site (NTSB)



Photo 5 - Rear View of Main Wreckage at Accident Site (NTSB)



Photo 6 – Overhead View of Wreckage at Recovery Facility (PIPER)



Photo 7 – Overhead View of Wreckage at Recovery Facility (PIPER)



Photo 8 – Overhead View of Wreckage at Recovery Facility (PIPER)



Photo 9 – Left Horizontal Stabilizer (PIPER)



Photo 10 – Rear View of Empennage and Portions of Wreckage (Piper)



Photo 11 – Right Forward Horizontal Stabilizer Spar (PIPER)



Photo 12 – Right Horizontal Stabilizer (PIPER)



Photo 13 – Forward View of Right Engine (NTSB)



Photo 14 – Right Engine and Six Fractured Propeller Blades (NTSB)



Photo 15 – Right Engine (NTSB)



Photo 16 - Right Engine (NTSB)