

From: [REDACTED]
To: [REDACTED]
Cc: [REDACTED]
Subject: ERA20LA216-Fuel line
Date: Tuesday, September 22, 2020 3:27:56 PM
Attachments: [IMG_3085.jpg](#)
[IMG_3089.jpg](#)

Pete,

The fuel line from the accident aircraft was submitted to the Materials Laboratory. The fuel line was a Parker Stratoflex 111F417-8d-0292 hose (1/2 in. inner diameter, synthetic rubber hose with fiberglass and steel wire braiding reinforcement with silicone fiberglass fire sleeving.) The full length of the hose was examined using a borescope. No blockages were observed and the interior of the hose appeared undamaged and intact. The fire sleeving was removed to visualize the exterior of the hose. No evidence of kinks, creases or material creep were observed on the exterior.

If you have any questions, please let me know.

Nancy B McAtee
Senior Chemist
RE-3-

