



**Photo 1 – Digital Photograph From Adam McCook. Left Side View of the Airplane at the Accident Site. Note the Extensive Damage to the Leading Edge of the Left Wing.**



**Photo 2 - Digital Photograph From Adam McCook. Left Side View of the Airplane at The Accident Site. Note the Compression Wrinkle in the Fuselage Near the Left Main Landing Gear Attach Point.**




**Photo 3 - Digital Photograph From Adam McCook. Forward View of the Airplane at The Accident Site. Note the Fire Damage in the Engine Compartment.**



**Photo 4 – Digital Photograph From Florida Air Recovery. Frontal View of the Engine Assembly Without Propeller Before Engine Postaccident Examination.**



**Photo 5 - Digital Photograph From Florida Air Recovery. View Showing the Fractured Throttle Body of the Carburetor. Note the Heat Damage in the Surrounding Area.**



**Photo 6 - Digital Photograph From Florida Air Recovery. View Showing the Carburetor Bowl and the Split Halves of the Brass Float.**



**Photo 7 - Digital Photograph From Florida Air Recovery. View Showing the Condition of the Spark Plugs.**



**Photo 8 - Digital Photograph From Florida Air Recovery. View Showing the Internal Condition of the Left Magneto. Note the Extensive Postimpact Heat Damage.**



**Photo 9 - Digital Photograph From Florida Air Recovery. View Showing the Internal Condition of the Right Magneto. Note the Extensive Postimpact Heat Damage.**