



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA20LA273



Photo 1 – View of Helicopter upon Recovery (Photo Courtesy of FAA)



Photo 2 – View of Helicopter from Front (Photo Courtesy of Airbus Helicopter)



Photo 3 – View of Helicopter from Left (Photo Courtesy of Airbus Helicopter)



Photo 4 – View of Helicopter from Rear (Photo Courtesy of Airbus Helicopter)



Photo 5 – View of Helicopter from Right (Photo Courtesy of Airbus Helicopter)



Photo 6 – View of Fenestron Fracture (Photo Courtesy of Airbus Helicopter)




Photo 7 – View of Engine (Photo Courtesy of Safran Helicopter Engines)