



MEMORANDUM FOR RECORD

Heidi Kemner
Air Safety Investigator
Eastern Region Aviation

September 10, 2020

Subject: ERA20LA278
Who: Kenneth Oddy – Airplane Mechanic

In a telephone conversation, Mr. Oddy stated the following:

- The pilot stated on occasion he said he was draining with contamination on right side.
- I did the first three test flights, and the engine was running good.
- Didn't see any issue during the install.
- He didn't share the issue with the right tank draining contaminants out of it until after the accident. I told him he should have said something, and we could have looked at it.