



Photo 1 – Digital Photograph From Insurance Adjuster. View of the Airplane on the Roof Before Recovery.



Photo 2 - Digital Photograph From Insurance Adjuster. View of the Airplane on the Roof Before Recovery.



Photo 3 – Digital Photograph From Federal Aviation Administration. View of a Portion of the Left Wing, Left Engine Assembly and Left Propeller.



Photo 4 - Digital Photograph From Federal Aviation Administration. Frontal View of the Airplane, Right Wing, Right Engine Assembly and Right Propeller After Recovery From Roof.



Photo 5 - Digital Photograph From Federal Aviation Administration. View of the Lower Portion of the Instrument Panel, and Throttle Quadrant While the Airplane was Suspended by the Roof.