



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Front View of Main Wreckage – Courtesy of FAA



Photo 3 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 4 – Rear View of Main Wreckage – Courtesy of FAA



Photo 5 – Right Side View of Main Wreckage – Courtesy of FAA




Photo 6 – Engine – Courtesy of FAA



Photo 7 – Firewall – Courtesy of FAA




Photo 8 – Mixture Control, Carburetor Heat Control, and Throttle Control – Courtesy of FAA



Photo 9 – Flap Handle – Courtesy of FAA



Photo 10 – Wing Flap – Courtesy of FAA




Photo 11 -Side View of Crankshaft Fracture – Courtesy of FAA



Photo 12 -Top View of Crankshaft Fracture – Courtesy of FAA



Photo 13 – Right Magneto – Courtesy of FAA




Photo 14 – Inside of Right Magneto – Courtesy of FAA




Photo 15 – Impact Damaged Bearing – Courtesy of FAA