



Photo 1 – View of the airplane inverted in the saltwater bay (Credit FAA)



Photo 2 – View of the airplane inverted in the saltwater bay (Credit FAA)



Photo 3 – View of right-wing substantial damage (Credit FAA)



Photo 4 – Overview of the engine (Credit FAA)



Photo 5 – View of the left-wing substantial damage (Credit FAA)