



MEMORANDUM FOR RECORD

Investigative Photographs
ERA20LA313

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

Photographs provided by the Federal Aviation Administration and Textron.



Photograph 1 – Accident Site – Left side of airplane.



Photograph 2 – Accident Site – Separated aft portion of fuselage.



Photograph 3 – Accident Site – Separated engine and landing gear.



Photograph 4 – Accident airplane – Post-examination of aft fuselage and left wing.



Photograph 5 – Accident airplane – Post-examination of fuselage and firewall.



Photograph 6 – Accident airplane – Post-examination of right wing.



Photograph 7 – Accident airplane – Post-examination of right wing.



Photograph 8 – Accident airplane – Post-examination of left wing.



Photograph 9 – Accident airplane – Post-examination of left wing.



Photograph 10 – Accident airplane – Post-examination of engine and propeller.



Photograph 11 – Accident airplane – Post-examination of cockpit instrument panel.



Photograph 12 – Accident airplane – Post-examination of cockpit instrument panel.