



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Right Side View of Main Wreckage – Courtesy of FAA



Photo 3 – Rear Underside View of Main Wreckage – Courtesy of FAA



Photo 4 – Left Side View of Main Wreckage – Courtesy of FAA



Photo 5 – Close Up Photo of Front of Wreckage – Courtesy of FAA



Photo 6 – Right Wingtip – Courtesy of FAA



Photo 7 – Right Aileron – Courtesy of FAA



Photo 8 – Right Fuel Tank – Courtesy of FAA



Photo 9 – Fuel Recovered from Wreckage – Courtesy of FAA



Photo 10 – Top View of Engine – Courtesy of UL Power



Photo 11 – Right Side View of Engine – Courtesy of UL Power



01/29/2021 10:24

Photo 12 – Left Side View of Engine – Courtesy of UL Power



01/29/2021 11:23

Photo 13 – Fuel Strainers, Filters, and Pumps – Courtesy of UL Power



Photo 14 – Inside of Fuel Filter – Courtesy of UL Power



Photo 15 – Oil Pickup Screen – Courtesy of UL Power



Photo 16 – Oil Pump – Courtesy of UL Power



Photo 17 – Interior of Left Side Rocker Boxes – Courtesy of UL Power



Photo 18 – Interior of Right Side Rocker Boxes – Courtesy of UL Power




Photo 19 – Camshaft and Lifters – Courtesy of UL Power



Photo 20 – Inside of oil Filter – Courtesy of UL Power