



Photo 1 – View of airplane inverted on beach after forced landing (also showing oil streaks on underside)



Photo 2 – View of airplane wreckage inverted showing oil streaking



Photo 3 – View of damaged vertical stabilizer and rudder



Photo 4 – View of crankshaft showing overheating on journals.