



Photo 1 – View of airplane resting on embankment. Both wings substantially damaged. Note panel embedded in leading edge of left wing. (Courtesy of FAA)



Photo 2 – Right profile view of airplane damage. Note solar panels in background. (Courtesy of FAA)



Photo 3 – View of left aft quarter of airplane and damage, with damaged solar panels in background. (Courtesy of FAA)



Photo 4 – Photograph of fuel inside gascolator. (Courtesy of FAA)



Photo 5 – Photograph of drained fuel and water. (Courtesy of FAA)



Photo 6 – Photograph of fuel, water and debris on bottom of container. (Courtesy of FAA)