



Photo 1 – View of Main Wreckage as Found (FAA)



Photo 2 – View of Engine During Recovery (FAA)



Photo 3 – View of Connecting Rod (FAA)



Photo 4 – View of Separated Cylinder after Recovery (FAA)



Photo 5 – View of Fractured Cylinder Mount Stud (FAA)