

NTSB Investigation: ERA20LA330

Photo Array



Photo 1 – View of the airplane inverted at the accident site (Photo Courtesy of FAA)



Photo 2 – Fragment of right wing in tree (Photo Courtesy of FAA)



Photo 3 – Curled tip of propeller blade (Photo Courtesy of FAA)



Photo 4 – View of tree in field being sprayed (Photo Courtesy of FAA)



Photo 5 – Broken branch near dead tree in field (Photo Courtesy FAA)



Photo 6 – Additional broken branch near dead tree in field (Photo Courtesy FAA)



Photo 7 – Separated agriculture spraying fan and piping found near dead tree (Photo Courtesy FAA)