



Photo 1 – View of the accident airplane at the accident site (Photo Courtesy of FAA)



Photo 2 - View of the left main landing gear collapsed under the fuselage (Photo Courtesy of FAA)



Photo 3 – Closer view of the left main landing gear collapsed under the fuselage (Photo Courtesy of FAA)




Figure 1 – View of the corrosion visible on the left landing gear airframe cross tube (Photo Courtesy of FAA)



Photo 4 – Closer view of the corrosion visible on the left landing gear airframe cross tube (Photo Courtesy of FAA)