



Photo 1 – View of airplane at wreckage site



Photo 2 – View of cockpit at wreckage site



Photo 3 – View of wreckage layout after recovery



Photo 4 – Aft view of layout after recovery



Photo 5 – Right wing view after recovery



Photo 6 – Right side of fuselage after recovery



Photo 7 – Empennage section after recovery




Photo 8 – Automotive installed fuel pump



Photo 9 – Rotax 912 ULS engine