



Photo 1 – NTSB Digital Photograph. View Looking Southwest Along Energy Path. Note the Wreckage in the Background, Impacted Car, and Separated Engine.



Photo 2 - NTSB Digital Photograph. View of Right Side of Impacted Car.



Photo 3 - NTSB Digital Photograph. View of the Separated Engine. Note the Wreckage in the Background.




Photo 4 - NTSB Digital Photograph. View of Front Portion of the Engine. Note the Insulated Powerline Wrapped Around the Crankshaft and the Separated Propeller.



Photo 5 - NTSB Digital Photograph. View Showing the Ground Scars and Resting Position of the Wreckage.



Photo 6 - NTSB Digital Photograph. Left Rear Quartering View of The Wreckage at the Accident Site.



Photo 7 - NTSB Digital Photograph. Left Side View Showing the Inboard Portion of the Left Wing, and Heat Damaged Cockpit and Cabin.



Photo 8 - NTSB Digital Photograph. View Looking North. Frontal View of the Resting Position of the Wreckage.



Photo 9 - NTSB Digital Photograph. View Depicting the Crease in the Right Side of the Car and Propeller in Approximate Position.



Photo 10 - NTSB Digital Photograph. Frontal View of the Separated Propeller.




Photo 11 - NTSB Digital Photograph. Pen points to Auxiliary Fuel Pump Switch.



Photo 12 – Continental Aerospace Technologies Digital Photograph. View of the Nos. 1, 3, and 5 Top Spark plugs. No. 1 is on the Left. Note the soot color.



Photo 13 - Continental Aerospace Technologies Digital Photograph. View of the Cylinder Portions of the Nos. 2, 4, and 6 Top Spark Plugs. No. 2 is on the Left. Note the soot color.



Photo 14 - Continental Aerospace Technologies Digital Photograph. View of the Cylinder Portions of the Nos. 1, 3, and 5 Bottom Spark Plugs. No. 1 is on the Left. Note the soot color for Nos. 3 and 5.



Photo 15 - Continental Aerospace Technologies Digital Photograph. View of the Cylinder Portions of the Nos. 4 and 6 Bottom Spark Plugs. No. 4 is on the Left. Note the soot color.




Photo 16 - Continental Aerospace Technologies Digital Photograph. View of the Cylinder Portions of All Top Spark Plugs Following the Last Full Power Engine Run. Note the Normal Color.




Photo 17 - Continental Aerospace Technologies Digital Photograph. Right Rear View of the Engine in the Test Cell Before Mounting Test Club Propeller.