



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21FA200



Photo 1 – View of helicopter from front



Photo 2 – View of helicopter from fractured tail cone



Photo 3 – View of tail rotor with gear box



Photo 4 – View of fractured tail rotor blade



Photo 5 – View of rotor blade tip with evidence of impact with the tail rotor guard



Photo 6 – View of rotor blade tip with evidence of wire strike



Photo 7 – View of tail rotor guard damage