



Photo 1 – View of Initial Tree Strike Facing Opposite Direction of Travel (Lycoming)



Photo 2 – View from Beneath Tree Strike Facing Direction of Travel (Lycoming)



Photo 3 – Angularly Cut Wood with Paint Transfer (Lycoming)



Photo 4 – S-Shaped Slash Marks Along Wreckage Path (Lycoming)



Photo 5 – Main Wreckage Facing Opposite Direction of Travel (Lycoming)



Photo 6 – View of Tail Section Adjacent to Main Wreckage (Lycoming)



Photo 7 – View of Left Propeller Tip Curl and Blade Polishing (Lycoming)



Photo 8 – View of Throttle Quadrant (Lycoming)