



Photo 1 – NTSB Digital Photograph. View of the Accident Site Depicting the nearly Consumed Airframe and Downed Tree.



Photo 2 - NTSB Digital Photograph. View of the Extensively Heat Damaged Engine Assembly At the Accident Site.



Photo 3 - NTSB Digital Photograph. View of the Extensively Heat Damaged Flap Motor/Actuator Assembly.



Photo 4 - NTSB Digital Photograph. View of the Accident Site Following Recovery and Clean-Up.



Photo 5 – Rotech Flight Safety Digital Photograph. Front and Top Views of the Extensively Heat Damaged Engine and Propeller Assembly Following Recovery.




Photo 6 - NTSB Digital Photograph. View of the Extensively Heat Damaged Carburetors. Note the Nos. 1/3 Carburetor is in the Foreground and the Nos. 2/4 Carburetor is in the Background.