



Photo 1 – View of Main Wreckage Facing Direction of Travel



Photo 2 – View of Left Wing and Main Landing Gear Leg



Photo 3 – Remains of Impact and Fire-Damaged Tail Section



Photo 4 – View of Engine, Firewall, and Remains of Instrument Panel



Photo 5 – View of Wreckage Path Opposite Direction of Travel



Photo 6 – View of Angularly Cut Wood at Accident Site



Photo 7 – Angularly Cut Branch at Accident Site