



Photo 1 – Main Wreckage – Courtesy of Buckingham County Emergency Management



Photo 2 – Front View of Main Wreckage



Photo 3 – Right Side View of Main Wreckage



Photo 4 – Right Rear View of Main Wreckage



Photo 5 – Left Rear View of Main Wreckage



Photo 6 - Cockpit



Photo 7 – Propeller and Engine



Photo 8 – Top of Engine Case Near No. 4 Cylinder



Photo 9 – Inside of Oil Sump



Photo 10 – Oil Filter Pleats



Photo 11 - Crankshaft



Photo 12 - Camshaft



Photo 13 – Connecting Rod



Photo 14 – Oil Quick Drain Leaking in Closed Position – Courtesy of Lycoming Engines



Photo 15 – Oil Quick Drain in Open Position – Courtesy of Lycoming Engines



Photo 16 – Oil Quick Drain Displaying Gold Coloration and Thermal Damage – Courtesy of Lycoming Engines




Photo 17 – Metallic Debris from Oil Sump – Courtesy of Lycoming Engines




Photo 18 – Exhaust Stack and Oil Quick Drain – Courtesy of Lycoming Engines



Photo 19 – Left and Right Exhaust Pipes



Photo 20 – Close Up of Left Side Exhaust Configuration