



Photo 1 – Digital Photograph From Nassau County Police Department Aviation Unit. Right Side View of the Helicopter. Note the Separated Doors and Displaced Crosstubes.



Photo 2 – Digital Photograph From Insurance Adjuster. Left side View of the Helicopter Following Recovery, also Depicting Recovered Tail Rotor Assembly.



Photo 3 - Digital Photograph From Insurance Adjuster. Right side View of the Helicopter Following Recovery.



Photo 4 - Digital Photograph From Federal Aviation Administration. View of the Tail Rotor Assembly Following Recovery.




Photo 5 - Digital Photograph From Federal Aviation Administration. View of the Tail Rotor Drive Shaft and Fractured Tail Rotor Control Fixed Tube Assembly.