



Investigative Photographs

Peter Wentz
Air Safety Investigator
Eastern Region Aviation

ERA21LA048

November 25, 2020



Photograph 1¹ – Accident airplane – left front view.

¹ Photograph provided by Federal Aviation Administration.



Photograph 2² – Left main gear strut.

² Photograph provided by Federal Aviation Administration.



Photograph 3³ – Accident airplane motor mount.

³ Photograph provided by Federal Aviation Administration.