



Photo 1 – Digital Photograph From Textron Aviation. View of the Wreckage at the Accident Site. Note the Extensive Damage.



Photo 2 - Digital Photograph From Textron Aviation. Another View of the Wreckage at the Accident Site. Note the Extensive Damage.



Photo 3 - Digital Photograph From Textron Aviation. View of the Reconstruction of the Left Wing. Redaction is of Wreckage Recovery Crew Member.



Photo 4 - Digital Photograph From Textron Aviation. View of the Right Wing.



Photo 5 - Digital Photograph From Textron Aviation. View of the Engine Assembly with Attached Propeller.



Photo 6 - Digital Photograph From Textron Aviation. View of the Recovered Airspeed Indicator.



Photo 7 - Digital Photograph From Textron Aviation. View of the Reconstruction of the Both Stabilizers and Elevators.



Photo 8 - Digital Photograph From Textron Aviation. Left Side View of the Engine Assembly with Attached Propeller After Cleaning off the Mud.




Photo 9 - Digital Photograph From AMF Aviation. Loose Elevator Control Cable retained For NTSB Examination. Note the Fractured Turnbuckle Eye.



Photo 10 - Digital Photograph From Textron Aviation. View of the Engine-Driven Vacuum Pump Following Removal of the Cover.