

NTSB Investigation: ERA21LA070

Photo Array



Photo 1 – View of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2 – Additional view of the airplane showing substantial damage to the right wing (Photo Courtesy of FAA)



Photo 3 – Additional view of the airplane showing substantial damage to the left wing (Photo Courtesy of FAA)



Photo 4 – View of the engine controls. The position of the carburetor heat lever was off (Photo Courtesy of FAA)



Photo 5 – View of the fuel selector selected to the right fuel tank. (Photo Courtesy of FAA)




Photo 6 – View of the engine cylinders during engine examination.
(Photo Courtesy of FAA)




Photo 7 – View of the engine cylinders during engine examination.
(Photo Courtesy of FAA)



Photo 8 – View of the carburetor bowl disassembled during engine examination (Photo Courtesy of FAA)