



Photo 1 – Main Wreckage (FAA Photo)



Photo 2 - Main Wreckage (FAA Photo)



Photo 3 - Empennage (FAA Photo)



Photo 4 – Rudder Cables (NTSB Photo)



Photo 5 – Nose Gear Damage (NTSB Photo)



Photo 6 - Rudder Cables (NTSB Photo)



Photo 7 – Bent Rod Between Rudder Pedals and Nose Landing Gear (NTSB Photo)