



Photo 1 – Digital Photograph From Daher. View Depicting the Wreckage Suspended in the Impacted Tree and Main Wreckage in the background.



Photo 2 - Digital Photograph From Daher. View Depicting the Separated Portion of the Left Wing in the Foreground, Right Wing and Main Wreckage in the Background.



Photo 3 - Digital Photograph From Daher. View Depicting The Right Wing, Separated Engine, and Fuselage. Note the Extensive Postcrash Fire Damage to the Cockpit and Cabin.



Photo 4 - Digital Photograph From Daher. View Depicting The Majority of the Right Wing. Note the Impact Damage to the Outer Leading Edge and the fire damage to the Inboard Section of the Wing.



Photo 5 - Digital Photograph From Daher. View Depicting The Inboard Portion of the Left Wing.



Photo 6 - Digital Photograph From Daher. View Depicting The Separated Engine Assembly.



Photo 7 - Digital Photograph From Daher. View Depicting The Separated Engine Assembly. Note the Fractured Crankshaft.



Photo 8 - Digital Photograph From Daher. View Depicting The Separated Propeller Assembly.