



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA091



Photo 1 – View of the airplane inverted where it came to rest. (Photo courtesy of FAA)



Photo 2 – View of the damage belly of the airplane. (Photo courtesy of FAA)



Photo 3 – View of the right side of the airplane. (Photo Courtesy of FAA)