



Photo 1 – View of the airplane and ground scarring from the runway excursion (Photo Courtesy of FAA)



Photo 2 – View of the substantially damaged left wing (Photo Courtesy of FAA)