



Memorandum For Record

Timothy W. Monville
Sr. Air Safety Investigator
Eastern Region

Date: March 21, 2023
NTSB Accident Number: ERA21LA106

A 47 second video (IMG_6300) taken from an airplane on the ramp with the engine running at Leesburg Executive Airport (JYO), Leesburg, Virginia was provided to NTSB. The airplane was east of the runway nearly in line with the fixed distance marker.

The video was looking to the north and zoomed in to show the airplane on final approach. As the airplane approached the runway a chase airplane was noted above and north of the accident airplane. The accident airplane continued the approach to the runway while descending then just before the fixed distance marker at an altitude less than the wing span of the airplane, with a view of the left side of the airplane, it landed hard on the nose landing gear and slid to a stop coming to rest upright on the runway just past the fixed distance marker. After coming to rest the chase airplane was observed flying over and past the airplane on the runway.

A 38 second video (IMG_6301) taken from an airplane on the ramp with the engine running at Leesburg Executive Airport (JYO), Leesburg, Virginia was provided to NTSB. The airplane was east of the runway near the approach end of the runway.

The video was looking to the north and depicted the airplane on final approach to the runway. As the airplane was descending to the runway from 11 seconds elapsed time, the left elevator was noted to be fluttering and continued to do so until just before runway contact. The video captured the airplane impacting the runway hard, and going out of view at 27 seconds elapsed time. At 33 seconds elapsed time the chase airplane was noted flying over the runway and at 35 seconds elapsed time the accident airplane was in view on the runway. The chase airplane was noted banking to the right and the video stopped.