




Photo 1 – FAA Digital Photograph. Frontal View of the Airplane on the Runway. Note the collapsed Nose Landing gear.



Photo 2 – FAA Digital Photograph. Left Side View Showing the Aft Empennage, Left Horizontal Stabilizer, Portion of the Vertical Stabilizer and rudder, and Displaced Left Elevator.



Photo 3 - FAA Digital Photograph. Left Side Close-Up View of the Damaged Outboard Rib of the Left Stabilizer, Displaced Left Elevator, and Portion of Vertical Stabilizer and Rudder.



Photo 4 - FAA Digital Photograph. Aft Side View of the Structurally Damaged Aft Spar of the Left Stabilizer, Portion of Displaced Left Elevator.



Photo 5 - FAA Digital Photograph. Close-Up View of the Aft Portion of the Outboard Rib of the Left Horizontal Stabilizer. Note the Missing section and Corrosion on the rib and also the Interior Surface of the Upper Skin.