

YEA
20
DAT

Date: December 15, 2020

N5880L Model: AA-5 S/N: AA5-0080 Tach: 2879.30 Hobbs: 515.1

C/W 100 HOUR inspection IAW AA-5 Maintenance Manual. Inspected ELT IAW FAR 91.207, next battery due change November 2021. Opened all inspection panels and inspected airframe, and lubed as required. Replaced Brackett air filter P/N BA4108. All AD'S accomplished through December 2020. I certify that this aircraft has been inspected I/AW an 100 HOUR inspection and was de [REDACTED] condition. Aircraft is okay for service.

DEAN J. DURBIN A&P [REDACTED]

January 13, 2021 N5880L Grumman AA-5 Tach: 2918.09

1. Removed flap motor assembly, cleaned limit switches, traced wiring from switch to check for electrical short.
2. Found Flap switch wired incorrectly, corrected same and installed 2 new electrical connectors.
3. Reassembled motor and switch.
4. Ops check satisfactory.

Aero Services of Winchester, Inc.

Winchester, VA [REDACTED]

[REDACTED]
Charlie Schoenduby A&P [REDACTED]