

<u>NATIONAL TRANSPORTATION SAFETY BOARD</u>		Time 10:00 am	Date 3/3/2021
RECORD OF: ☐ VISIT ☐ CONFERENCE ☒ TELEPHONE CALL			
Name (s) of Person (s) contacted or in conference and location Mr. Jonathan Behnke-Pilot		Routing	
		Symbol	Initials
		ERA	EA
Subject: N7832X-Winchester, VA. (carburetor icing event)			
Digest: In a telephone review of Mr. Behnke 6120.1 accident/incident form he stated: "I believe the issue with the plane could have been carburetor icing. When I was at KOKV waiting for my turn to depart 3 aircraft landed then one aircraft took off before me, it was a good 30 min wait time. In the future, I plan to use my carb heat on the ground if I am waiting in line to depart." Mr. Behnke felt that waiting on the ground for a extended period of time contributed to the outcome of this event.			
Conclusions, Action Taken, or Required: This correspondence was reviewed with pilot			
Date 3/3/2021	Title ASI	Signature Alleyne	