



Photo 1 – Tail view of main wreckage



Photo 2 – view of main wreckage, left wing



Photo 3 – Bent motor mount (FAA)