



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA166



Photo 1 – View of the right side of the airplane. (Photo Courtesy of FAA)



Photo 2 – View of the damage to the left wing. (Photo Courtesy of FAA)



Photo 3 – View of the instrument panel. (Photo Courtesy of FAA)