



MEMORANDUM FOR RECORD

Heidi Kemner
Air Safety Investigator
Eastern Region Aviation

May 11, 2021

Subject: ERA21LA181
Who: Shane Olsen – FAA Inspector

In a telephone conversation, Inspector Olsen stated the following:

- After the accident, he examined the wreckage and noted that the flaps were in the first notch position.
- He attempted to move the handle; however, it was welded in place as a result of the postaccident fire.