



Photo 1 – View of the airplane submerged in water at the accident site (Photo Courtesy of FAA)



Photo 2 – View of the substantially damaged fuselage and empennage (Photo Courtesy of FAA)




Photo 3 – Overview of the engine



Photo 4 – Internal view of the right magneto