



Photo 1 – View of damaged leading edge of vertical stabilizer



Photo 2 -View of buckled vertical stabilizer spar.