



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA198



Photo 1 – View of airplane from front (Photo Courtesy of FAA)



Photo 2 – View of damage to the left horizontal stabilizer (Photo Courtesy of FAA)