



Photo 1 – Drone Image Fm Lakeland Linder International Airport Individual. Aerial View of the Wreckage at the Accident Site. White Sheet Covering Registration Markings.



Photo 2 - Drone Image Fm Lakeland Linder International Airport Individual. Aerial View Looking From near Impacted Palm tree Towards Resting Position of Main Wreckage.



Photo 3 - Drone Image Fm Lakeland Linder International Airport Individual. Aerial View Looking Down at Main Wreckage.




Photo 4 – Textron Aviation Digital Photograph. Left Side View of the Engine Assembly with Attached Propeller Following Recovery. Note the Minimal Bending of Both Propeller Blades.



Photo 5 - Textron Aviation Digital Photograph. View of the Throttle Body and Metering Valve.



Photo 6 - Textron Aviation Digital Photograph. View of the Engine-Driven Fuel Pump and Intact Drive Coupling.




Photo 7 - Textron Aviation Digital Photograph. View of the NTSB Retained Fuel System Parts for Testing at Continental Aerospace Technologies.



Photo 8 - Textron Aviation Digital Photograph. View of the Fuel Injector Nozzles.



Photo 9 - Textron Aviation Digital Photograph. View of the Organic Material Removed from the No. 1 Cylinder Fuel Injector Nozzle.



Photo 10 – Continental Aerospace Technologies Digital Photograph. View of the Manifold Valve or Flow Divider with Attached Fuel Injector Lines and Separated Fuel Injector Nozzles Prior to Testing.