



Photo 1 – View of right main landing gear brake assembly showing fire damage



Photo 2 – View of right wing assembly showing fire damage



Photo 3 – View of right brake assembly hydraulic hose fitting, showing fire damage