



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA213



Photo 1 – View of airplane from right (Photo Courtesy of FAA)



Photo 2 – View of damage to the bottom of the cowling (Photo Courtesy of FAA)



Photo 3 – View of engine with cowling removed (Photo Courtesy of FAA)



Photo 4 – View of disassembled carburetor (Photo Courtesy of FAA)