



Photo 1 – View of the substantially damaged left elevator (Photo Courtesy of FAA)



Photo 2 – View of the damaged left main landing gear assembly (Photo Courtesy of FAA)



Photo 3 – Additional view of the left main landing gear damage (Photo Courtesy of FAA)



Photo 4 – View of the debris found on the runway after taxiway sign impact (Photo Courtesy of Airport Authority)