



Photo 1 – View of empennage damage. (Courtesy of FAA)



Photo 2 – View of elevator and tail damage. (Courtesy of FAA)



Photo 3 – View of right inboard wing damage. (Courtesy of FAA)



Photo 4 – View of cockpit instrument panel. (Courtesy of FAA)