



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Eastern Region

Photo Array

ERA21LA291



Photo 1 – View of the damage to the leading edge. (Photo Courtesy of FAA)



Photo 2 – View of the damage to the horizontal stabilizer. (Photo Courtesy of FAA)