

NTSB Investigation: ERA21LA295

N4529J | Robinson R44 II

Photo Array



Photo 1 – View of a portion of the helicopter's airframe and fuel tank cap as recovered by the United States Coast Guard (Photo Courtesy of USCG)



Photo 2 – Additional view of the helicopter's airframe displaying the model type, as recovered by the United States Coast Guard (Photo Courtesy of USCG)



Photo 3 – Seat cushions and checklist recovered by the United States Coast Guard (Photo Courtesy of USCG)